

## Photographic Representations of Treatment Types



Cross Vane Structure on Cheyenne Creek below I-25 Overpass. Colorado Springs, El Paso County, Colorado



Cross Vane Structure on Fountain Creek below 21<sup>st</sup> Street Bridge, El Paso County, CO.





Cottonwood trees used as toe-slope stabilization with riparian benches. Cucharas Creek, Huerfano County, Colorado.



Boulders placed in clusters to create pocket water micro vortex habitats. South Platte River, Park County, CO.





Picketwire Canyonlands, SE Colorado - Rock vanes used to protect dinosaur trackway. These structures were installed in 1998, and survived a 100 year event the following spring. Note the deposition and new willow vegetation taking hold in between the structures. The photo below shows the Project nine years later.



Aerial of Dinosaur Tracks along Purgatoire River  
 Picket Wire Canyonlands, Comanche National Grassland, southeastern Colorado  
 Copyright 2007 Wendy Shattil/Bob Rozinski [www.dancingpelican.com](http://www.dancingpelican.com)  
 Permission of USDA Forest Service





Eagle Rock Ranch - Rock J-Hook Vanes installed to protect stream banks and adjacent road,, 2003.